



WYTWÓRNIA SPRZĘTU KOMUNIKACYJNEGO  
„PZL-ŚWIDNIK”

**LIST  
OF SERVICE NOTES  
AND BULLETINS**

**FOR**

**Mi-2 HELICOPTERS**

**OPERATED  
IN MYANMAR AVIATION**

**Doc. No. WB-5B**

**CONTENTS**

**1. LIST OF SERVICE NOTES ..... 3**

**2. LIST OF BULLETINS ..... 4**

**„PZL-ŚWIDNIK”**  
**LIST OF SERVICE NOTES**

Item	Service Note No.	Subject	Effectivity	Date of approval	Revision number and its approval date	Language version
1.	NE-514005	Modifications and changes possible to be introduced on helicopters operated in Myanmar.	All helicopters	10.07.2001		P

**„PZL-ŚWIDNIK”****LIST OF BULLETINS**

Item	Bulletin No.	Subject	Effectivity	Date of approval	Revision number and its approval date	Language version
1.	50-E-001/04 Mandatory	Check of melt number and replacement of bolts 50.39.100.25.03 securing pitch links in tail rotor feathering hinges.	All helicopters	20.04.2004		P, E
2.	50-E-002/06 Mandatory	Non-recurring inspection of main gearbox mounting plate attachment points.	All helicopters	19.09.2006		P, E
3.	50-E-003/06 Mandatory	Non-recurring inspection of roof structure for technical condition in RH engine internal attachment point and repair of detected damages.	All helicopters	19.09.2006		P, E
4.	50-E-004/09 Mandatory	Inspection of frames 1F and 2F for cracks at location of roof structure reinforcing brackets in engine attachment points.	All helicopters	16.01.2009		P, E