



WYTWÓRNIA SPRZĘTU KOMUNIKACYJNEGO
„PZL-ŚWIDNIK”

**LIST
OF SERVICE LETTERS
AND BULLETINS
FOR
PZL W-3A HELICOPTERS
OPERATED
BY ALGERIAN OPERATOR**

Doc. No. WB-3DZ

CONTENTS

1. LIST OF SERVICE LETTERS 3

2. LIST OF BULLETINS 4

„PZL-ŚWIDNIK”
LIST OF SERVICE LETTERS

| Item | Service Letter No. | Subject | Effectivity | Date of approved | Revision number and its approval date | Language version |
|------|--------------------|--|--|------------------|---------------------------------------|------------------|
| 1. | LS-018/2013 | Replacement of Shield Assy P/N 37.61.621.00.00 with Shield Assy P/N 37.61.621.00.01 in Auxiliary Fuel Tank Assy P/N 37.61.620.00.00. | Auxiliary Fuel Tank Assy, P/N 37.61.620.00.00, S/N 003 and 004, operated on the PZL W-3A helicopters | 29.10.2013 | | P, E |
| 2. | LS-067/2014 | Engine Compartment Firewalls. | PZL W-3A helicopters S/N 37.10.02; 37.10.03; 37.10.04; 37.10.05; 37.10.06; 37.10.07; 37.10.08 | 29.08.2014 | | P, E |
| 3. | LS-085/2015 | Operation of the PZL W-3A helicopters which have local discoloration on the MR blade abrasion strips. | MR blades installed on helicopters S/N 37.10.01 thru 37.10.08, and blades delivered as loose items | 26.08.2015 | | P, E |
| 4. | LS-086/2015 | Operation of the PZL W-3A helicopters which have defects of MR blades at mooring sockets. | MR blades installed on helicopters S/N 37.10.01 thru 37.10.08 | 26.08.2015 | | P, E |
| 5. | LS-103/2016 | Maintenance activities for KAC 1052 Antenna Coupler. | PZL W-3A helicopters S/N 37.10.01 thru 37.10.08 | 30.05.2016 | | P, E |

„PZL-ŚWIDNIK”

LIST OF BULLETINS

| Item | Bulletin No. | Subject | Effectivity | Date of approved | Revision number and its approval date | Language version |
|------|------------------|--|--|------------------|---------------------------------------|------------------|
| 1. | BT-37-14-01/DZ | 1. Introduction of relay to heating and ventilation system, Dwg. 37.74.210.00.00. 2. Introduction of diodes to harness assembly connector 1429, Dwg. 37.72.620.00.01. | PZL W-3A helicopters: - S/N 37.10.01 thru 37.10.06, for relay, - S/N 37.10.04 and 37.10.05, for diodes | 10.03.2014 | | P, E |
| 2. | BK,E-37-14-02/DZ | 1. Installation of LED anti-collision lights type 01-0771080-01 made by WHELEN, instead of lights A470A. 2. Updating helicopter Manuals. | PZL W-3A helicopters S/N 37.10.01 thru 37.10.08 | 20.10.2014 | | P, E |
| 3. | BK-37-15-03/DZ | Engine compartment firewalls. | PZL W-3A helicopters S/N 37.10.02 thru 37.10.08 | 08.06.2015 | | P, E |