



WYTWÓRNIA SPRZĘTU KOMUNIKACYJNEGO
„PZL-ŚWIDNIK”

**LIST
OF SERVICE LETTERS
AND BULLETINS
FOR
PZL W-3A HELICOPTERS
OPERATED
IN PHILIPPINES MILITARY AVIATION**

Doc. No. WB-3PH

CONTENTS

1. LIST OF SERVICE LETTERS 3

2. LIST OF BULLETINS 4

„PZL-ŚWIDNIK”

LIST OF SERVICE LETTERS

Item	Service Letter No.	Subject	Effectivity	Date of approved	Revision number and its approval date	Language version
1.	LS-012/2013	Operation of helicopters without Movable MR Blade Droop Stops P/N 37.21.800.00.00.	W-3A Helicopters (from S/N 31.09.19 to S/N 31.09.26)	05.02.2013		P, E
2.	LS-013/2013	Replacement of Access Cover P/N 37.17.369.00.00 (with slots) with Access Cover P/N 30.15.272.00.01 (without slots).	W-3A Helicopters (from S/N 31.09.19 to S/N 31.09.26)	12.06.2013		P, E
3.	LS-026/2013	Restoring Operation of Helicopters with Movable MR Blade Droop Stops.	W-3A Helicopters (from S/N 31.09.19 to S/N 31.09.26)	28.10.2013		P, E
4.	LS-034/2013	Rework of riveted joint in Plate P/N 30.13.000.15.01 to comply with tail boom structure.	W-3A Helicopters (from S/N 31.09.19 to S/N 31.09.26)	22.10.2013		P, E
5.	LS-040/2013	Rear Tip Cap P/N 30.29.005.20.05 of PZL W-3A Helicopter Main Rotor Blade P/N 30.29.000.00.03.	Main Rotor Blade, S/N 30.09.673	22.11.2013		P, E

„PZL-ŚWIDNIK”

LIST OF BULLETINS

Item	Bulletin No.	Subject	Effectivity	Date of approved	Revision number and its approval date	Language version
1.	K-31-12-01/PH	1. Installation of additional ventilation system in LH avionics compartment and tail boom. 2. Updating helicopter manuals.	PZL W-3A helicopters: -S/N 31.09.19÷22 - installation; - All helicopters - manuals updating	04.12.2012		P, E
2.	K,E-31-12-02/PH	1. Installation of SC50 inverter instead of PC-351. 2. Updating operation and maintenance manuals.	PZL W-3A helicopters: -S/N 31.09.19÷22 - installation; - All helicopters - manuals updating	27.11.2012		P, E
3.	E-31-13-03/PH	Updating Flight Manual, Doc. No. AE-31.09.19.0 RFM.	All PZL W-3A helicopters	21.02.2013		P, E
4.	BO-31-13-04/PH Mandatory	One-time inspection of tail rotor pylon plate for cutout ensuring required clearance for tail rotor control cables.	PZL W-3A Helicopters (from S/N 31.09.19 to 31.09.26)	11.10.2013		P, E
5.	BS-31-13-05/PH	Updating Maintenance Manual, Doc. No. AE-31.09.19.0 MM.	All PZL W-3A helicopters	16.01.2014		P, E
6.	BE-31-16-06/PH	Updating Helicopter Maintenance Manual, Doc. No. AE-31.09.19.0 MM.	All PZL W-3A helicopters	13.03.2017		P, E
7.	BK,E-31-17-07/PH	1. Installation of electronic backup control units, type ALRT-2E, on the PZL-10W engines. 2. Updating helicopter manuals.	PZL W-3A helicopters: - for installation – in accordance with Purchase Order; - for updating manuals - all	03.07.2017		P, E